F/G. 1




FIG. 3A







FIG. 3B



F1G. 3C



Best Available Copy



Best Available Copy

## DESCRIPTION OF REFERENCE NUMERALS

- 1 .... die
- 1a ···· three-dimensionally curved surface part of the die
- 1' ···· die coated with a photoresist
- 1" ···· etching-finished die
- 2 ···· photomask
- 2' ···· mold-finished photomask
- 3 ···· far-infrared ray heater
- 4 ··· die for vacuum mold
- 11, 13, 13.... photomasks
- 20 ···· die coated with a photoresist
- 20a ···· seam on die surface